X0X09422595-051 SC PPW 12/1/2008 Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form Approved. OMB No. 2050-0039 UNIFORM HAZARDOUS 1. Generator ID Number 3. Emergency Response Phone 4. Manifest Tracking Number 2. Page 1 of NSD007246846 08 WASTE MANIFEST Generator's Name and Mailing Address Generator's Site Address (if different than mailing address) 2549 North New York Street SAME Wichita KS 67219 (316) 269-7400 987347515 Generator's Phone: 6. Transporter 1 Company Name Glear Husbars, Engrances tal Services (ne MAD039322250 7. Transporter 2 Company Name U.S. EPA ID Number 8. Designated Facility Name and Site Address U.S. EPA ID Number Clean Harbors Lone Mountain LLC 40368 S County Road 236 OKD065438376 Wayneka, OK 73860 (580) 697-3500 Facility's Phone: 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, 9a. 10. Containers 11. Total 12 Unit and Packing Group (if any)) 13. Waste Codes HM No. Туре Quantity Wt. Vol. 1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), B, FOOL F002 F003 POH × 16 DI F004 FOOD 2. 14. Special Handling Instructions and Additional Information 1.CH831502W0B ERG\$171 GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. Generator's/Offeror's Printed/Typed Name Month Year e gallerthis 0 INT.L 16. International Shipments Import to U.S. Export from U.S. Port of entry/exit: Transporter signature (for exports only): Date leaving U.S. TR ANSPORTER 17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Signature Transporter 2 Printed/Typed Name Signature Month Day Year 18. Discrepancy 18a. Discrepancy Indication Space Туре Quantity Residue Partial Rejection Full Rejection Manifest Reference Number: DESIGNATED FACILITY 18b. Alternate Facility (or Generator) U.S. EPA ID Number Facility's Phone 18c. Signature of Alternate Facility (or Generator) Month Day Year 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. 1912.32

Signature

Printed/Typed Name

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

Day

Year

Month

4

X0X09422595-051 SC PPW 12/1/2008 Please print or type. (Form designed for use on elite (12-pitch) typewriter. Form Approved. OMB No. 2050-0039 UNIFORM HAZARDOUS 1. Generator ID Number 2. Page 1 of 3. Emergency Response Phone 4. Manifest Tracking Number KSD007246846 (800) 483-37:18 WASTE MANIFEST Generator's Name and Mailing Address Generator's Site Address (if different than mailing address) 2549 North New York Street SAME Wichita, KS 67219 Generator's Phone: (316) 269-7400 6. Transporter 1 Company Name Gleen-Harbors Emirronnestal Germon-Inc MAD039322250 7. Transporter 2 Company Name U.S. EPA ID Number 8. Designated Facility Name and Site Address U.S. EPA ID Number Clean Harbors Lone Mountain LLC 40355 S County Road 236 OKD065438376 Waynoka, OK 73960 Facility's Phone: 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, 10. Containers 12. Unit 11 Total 13. Waste Codes and Packing Group (if any)) НМ Quantity Wt./Vol. No. Туре NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9. 8-57 FOOL F002 F003 GENERATOR POIN X F004 F005 14. Special Handling Instructions and Additional Information 1.CH831502X0B ERGS171 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. Generator's/Offeror's Printed/Typed Name J. W. TVE 16. International Shipments Export from U/S Port of entry/exit: Transporter signature (for exports only): Date leaving U.S. 17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed Typed Name Transporter 2 Printed/Typed Name R 18. Discrepancy 18a. Discrepancy Indication Space Full Rejection Quantity Residue Partial Rejection Manifest Reference Number: 18b, Alternate Facility (or Generator) DESIGNATED FACILITY U.S. EPA ID Number Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Month Day Year

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

H132

Clean Harbers has the appropriate permits for and will accept the waste the generator is shipping

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

DESIGNATED FACILITY TO GENERATOR